

Refurbishment



- Retrofitting of existing electrostatic precipitators by
- adaption of our control equipment to the installed control cabinets,
- the main power circuits remain,
- the door openings are adjusted by sheet panels,
- the transformer rectifier sets remain unchanged,
- if necessary, the secondary voltage signal is connected to external dividers.
- State-of-the-art control technology improves precipitation results and optimizes energy consumption.